STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	B044002	A. BUILDING: _____ B. WING _____	09/01/2020

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
KELLY HOUSE OF MERIDEN SOUTH	3566 62ND STREET MERIDEN, KS 66512

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S 000	INITIAL COMMENTS The following citations are the result of a survey for re-licensure conducted on 8/31/20 and 9/1/20 at the above named home plus facility in Meriden, KS.	S 000		
S5380 SS=F	28-39-437 Plumbing and Piping Systems (i) Plumbing and piping systems. (1) Backflow prevention devices or vacuum breakers shall be installed on fixtures to which hoses or tubing can be attached. (2) Water distribution systems shall be arranged to provide hot water at hot water outlets at all times. The temperature of hot water shall range between 98° F and 120° F at showers, tubs, and lavatories accessible to residents. This REQUIREMENT is not met as evidenced by: KAR 28-39-437(i)(2) The facility reported a census of 8 residents. The sample included 3 residents. Based on observation, record review and interview for all residents, the operator failed to ensure the facility water distribution system maintained a safe hot water temperature between 98 and 120 degrees Fahrenheit at the sinks in resident use areas. Findings included: - Facility tour with operator #A on 8/31/20 from 12:53pm until 1:45pm revealed water temperatures as follows:	S5380		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	B044002	A. BUILDING: _____ B. WING _____	09/01/2020

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
KELLY HOUSE OF MERIDEN SOUTH	3566 62ND STREET MERIDEN, KS 66512

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S5380	Continued From page 1 Facility open concept kitchen sink: 123.8F (degrees Fahrenheit). North resident bathroom/shower room: shower: 125.4F South resident bathroom/shower room: sink 123.4F Recheck of facility sinks on 8/31/20 at 1:45pm with operator #A revealed water temperatures as follows: Facility open concept kitchen sink: department thermometer (DT): 126.5F: facility thermometer (FT): 124.0F North resident/public bathroom/shower room sink: DT: 127.2F: FT: 126.0F South resident bathroom/shower room sink: DT: 126.6F: FT: 124.0F Recheck of facility sinks on 9/1/20 at 11:33am revealed the following sink temperatures: Facility open concept kitchen sink: DT: 126.8F North resident bathroom/shower room sink: DT: 118.4F South resident bathroom/shower room sink: DT: 128.8F Interview on 9/1/20 at 11:30am with licensed nurse #B stated the corporate maintenance director was coming later to check the hot water heaters. She then called for assistance and was instructed how to turn down the thermostat on the hot water heaters. Observed her adjust the hot water heater in the laundry room. Resident roster recorded all residents have problems with cognition.	S5380		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	B044002	A. BUILDING: _____ B. WING _____	09/01/2020

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
KELLY HOUSE OF MERIDEN SOUTH	3566 62ND STREET MERIDEN, KS 66512

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S5380	Continued From page 2 Facility hot water temperature logs for August recorded temperatures between 110F to 120F for 8/3/20 to 8/31/20. Log recorded checks completed weekly on each Monday. Facility policy titled: Water Temps recorded: Ensure patient room water temperatures are between 105F and 115F or as specified by state requirements. Test temperature in shower areas, common area bathrooms, public bathrooms and any other areas having sinks should be checked and recorded as well. Note any discrepancies, adjust water heater settings as required and retest as necessary. For all residents of the facility, the operator failed to ensure the facility water distribution system maintained a safe hot water temperature between 98 and 120 degrees Fahrenheit at the sinks in resident use areas.	S5380		