STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	B087153	A. BUILDING: _____ B. WING _____	06/28/2022

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ACCORD SENIOR CARE INC - ROCKWOOD	6807 E ROCKWOOD ROAD WICHITA, KS 67206

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S 000	INITIAL COMMENTS The following citations represent the findings of the licensure resurvey for the above named facility conducted on 06/28/22.	S 000		
S5380 SS=F	28-39-437 Plumbing and Piping Systems (i) Plumbing and piping systems. (1) Backflow prevention devices or vacuum breakers shall be installed on fixtures to which hoses or tubing can be attached. (2) Water distribution systems shall be arranged to provide hot water at hot water outlets at all times. The temperature of hot water shall range between 98° F and 120° F at showers, tubs, and lavatories accessible to residents. This REQUIREMENT is not met as evidenced by: KAR 28-39-437(i)(2) The facility reported a census of five residents. Based on observation and interview the operator failed to ensure water temperatures were maintained within a safe range between 98 degrees Fahrenheit (F) and 120 degrees F. During initial tour of the facility, the hot water temperature in the main bathroom that was used by all residents for bathing measured 134.2 degrees F. Findings included: - Observation on 06/28/22 at 12:22 PM revealed the water temperature in Resident (R) 630's bathroom sink measured 125.4 degrees Fahrenheit (F) Observation on 06/28/22 at 12:24 PM revealed	S5380		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	B087153	A. BUILDING: _____ B. WING _____	06/28/2022

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ACCORD SENIOR CARE INC - ROCKWOOD	6807 E ROCKWOOD ROAD WICHITA, KS 67206

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S5380	Continued From page 1	S5380		

the water temperature in R628's bathroom sink measured 123.2 degrees F.

Observation 06/28/22 at 12:46 PM revealed the water temperature in the sink of the main shower room measured 134.2 degrees F.

Observation on 06/28/22 at 04:24 PM revealed the water temperature in the sink of the main shower room measured 116.8 degrees F.

On 06/28/22 at 01:30 PM Administrative Staff A stated she was responsible for obtaining water temperatures throughout the facility. She kept a log and obtained temperatures twice a month on the first and the fifteenth. The last water temperature she obtained was on 06/01/22 and was 118 degrees F. Resident baths were always supervised or assisted. Only two residents were cognitively impaired who had access to the hot water for showering or washing hands but were always assisted to shower and supervised to wash hands.

On 06/28/22 at 01:36 PM Certified Nurse Aid (CNA) B stated she always felt the water first to make sure it was warm before letting residents wash their hands or take a shower. It had never felt too hot.

On 06/28/22 at 01:36 PM Administrative Staff A stated she adjusted down the thermostats on both water heaters for the facility.

On 06/28/22 at 04:39 PM Administrative Staff A stated she did not check the water temp on 06/15/22 like usual because she had checked it on 06/01/22 and it was fine. She thought the temperature would not change so quickly.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	B087153	A. BUILDING: _____ B. WING _____	06/28/2022

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ACCORD SENIOR CARE INC - ROCKWOOD	6807 E ROCKWOOD ROAD WICHITA, KS 67206

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S5380	Continued From page 2 The operator failed to ensure water temperatures were maintained within a safe range between 98 degrees Fahrenheit (F) and 120 degrees F.	S5380		